



Fig. 1 Power-Pipe end enlargement from Fig 2 below shows coils are soldered directly to drainpipe. This does not meet double-wall venting requirement of [UL File SA8583 \(7/92\)](#); the original GFX safety certification licensed to Doucette Insustries then pirated by Renewability.

POWER-PIPE
...is the Clear Leader
Among DWHR
Technologies

A promotional graphic for Power-Pipe technology. It features a blue background with the text "POWER-PIPE" in large, bold, orange letters with a red arrow pointing right and a blue arrow pointing left. Below this, the text "...is the Clear Leader Among DWHR Technologies" is written in white. On the right side, there is a partial view of the pipe and coils from Fig. 1.

Fig. 2 Photo of un-certifiable Power-Pipe from http://www.renewability.com/power_pipe/index.html